





Reducing Washers



- Use to reduce the size of the knockout in a steel outlet box
- or other metal enclosure or cabinet
- Must use one inside the enclosure opening and one on the outside
- Galvanized Steel

CAT. NO.	TRADE SIZE	DIMENSIONS		INNER BOX	OUTER BOX
		A	B		
I4620	3/4" X 1/2"	1.44"	0.87"	100	1,000
I4621	1" X 1/2"	1.71"	0.87"	100	1,000
I4622	1" X 3/4"	1.74"	1.10"	100	1,000
I4623	1-1/4" X 1/2"	2.08"	0.87"	50	500
I4624	1-1/4" X 3/4"	2.08"	1.125"	50	500
I4625	1-1/4" X 1"	2.08"	1.38"	50	500
I4626	1-1/2" X 1/2"	2.635"	0.87"	50	500
I4627	1-1/2" X 3/4"	2.635"	1.06"	50	500
I4628	1-1/2" X 1"	2.635"	1.335"	50	500
I4629	1-1/2" X 1-1/4"	2.635"	1.69"	50	500
I4630	2" X 1/2"	3.265"	0.87"	25	250
I4631	2" X 3/4"	3.265"	1.06"	25	250
I4632	2" X 1"	3.265"	1.335"	25	250
I4633	2" X 1-1/4"	3.265"	1.69"	25	250
I4634	2" X 1-1/2"	3.265"	1.935"	25	250


Locknuts - Zinc Die Cast



- Conduit locknuts for securing threaded conduit or connectors with tapered or straight thread, to a knockout or unthreaded slip hole

CAT. NO.	TRADE SIZE	DIMENSIONS		INNER BOX	OUTER BOX
		A	B		
I4720	1/2"	1.09"	0.12"	100	4,000
I4721	3/4"	1.36"	0.14"	100	2,500
I4722	1"	1.66"	0.16"	50	1,000

Locknuts - Steel



- Conduit locknuts for securing threaded conduit or connectors with tapered or straight thread, to a knockout or unthreaded slip hole

CAT. NO.	TRADE SIZE	DIMENSIONS		INNER BOX	OUTER BOX
		A	B		
I4760	1/2"	1.13"	0.10"	-	1,000
I4761	3/4"	1.39"	0.10"	-	1,000
I4762	1"	1.71"	0.13"	-	1,000
I4763	1-1/4"	2.07"	0.13"	50	500
I4764	1-1/2"	2.39"	0.13"	50	500
I4765	2"	2.88"	0.13"	25	250
I4766	2-1/2"	3.45"	0.16"	-	100
I4767	3"	4.14"	0.16"	-	100
I4768	3-1/2"	4.70"	0.16"	-	100
I4769	4"	5.30"	0.16"	-	100
I4770	5"	6.51"	0.37"	-	20
I4771	6"	7.85"	0.37"	-	20